

Michael O. Leavitt

Governor

DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple, Suite 1210 PO Box 145801

Salt Lake City, Utah 84114-5801

Kathleen Clarke 801-538-5340 **Executive Director**

801-359-3940 (Fax) Lowell P. Braxton 801-538-7223 (TDD) Division Director

INSPECTION REPORT

Partial: XXX Con	Complete:		Exploration:			
Inspection Date & Time:	07/27 & 3	1/2001	/ 9:00 - 15:00			
Date of Last Insp	ection: 06/1	3 & 26	/2001			


Mine Name: Crandall Canyon Mine County: Emery Permit Number: C/015/032							
Permittee and/or Operator's Name: Genwal Resources, Inc.							
Business Address: P.O. Box 1420, Huntington, Utah 84528							
Type of Mining Activity: Underground XXX Surface Prep. Plant Other							
Company Official(s): Gary Gray							
State Official(s): Bill Malencik, Karl Houskeeper Federal Official(s): None							
Weather Conditions: Partly Cloudy, 90's							
Existing Acreage: Permitted 5195.8 Disturbed 10.7 Regraded Seeded Seeded							
Status: Active XXX							

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	<u>N/A</u>	<u>COMMENTS</u>	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]		Ц	
2.	SIGNS AND MARKERS	[X]	П	[X]	\Box
3.	TOPSOIL	[X]	\Box	П	\Box
4.	HYDROLOGIC BALANCE:				
	a. DIVERSIONS	[X]	\Box	[X]	\Box
	b. SEDIMENT PONDS AND IMPOUNDMENTS	[X]	П	[X]	
	c. OTHER SEDIMENT CONTROL MEASURES	[X]	П	П	
	d. WATER MONITORING	[X]	\Box	[X]	
	e. EFFLUENT LIMITATIONS	[X]	П	[X]	П
5.	EXPLOSIVES	[X]	\Box		\Box
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[X]	\Box	П	
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[X]	П	П	
8.	NONCOAL WASTE	[X]	Ш	[X]	
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				
	ENVIRONMENTAL ISSUES	П	П	П	П
10.	SLIDES AND OTHER DAMAGE	П	П	П	П
11.	CONTEMPORANEOUS RECLAMATION	П			$\overline{\Box}$
12.	BACKFILLING AND GRADING	$\overline{\Box}$	\Box	П	П
13.	REVEGETATION	$\overline{\Box}$	\Box	$\overline{\Box}$	$\overline{\Box}$
14.	SUBSIDENCE CONTROL	: <u> </u>	$\overline{\Box}$	<u> </u>	$\overline{\Box}$
15.	CESSATION OF OPERATIONS		П	Π	
16.	ROADS:	20			
	a. CONSTRUCTION/MAINTENANCE/SURFACING	[X]	П	[1]	П
	b. DRAINAGE CONTROLS	[X]	\Box	Ū	
17.	OTHER TRANSPORTATION FACILITIES	[X]		П	П
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[X]	П	П	П
19.	AVS CHECK (4th Quarter- April, May, June)	П	Ц	П	$\overline{\Box}$
	AIR QUALITY PERMIT	$\overline{\Box}$	\Box	$\overline{\Box}$	
	BONDING & INSURANCE	$\overline{\Box}$	$\overline{\Box}$	$\overline{\square}$	$\overline{\Box}$

DATE OF INSPECTION: <u>07/27 & 31/2001</u>



(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

GENERAL COMMENTS

Performed a partial inspection of the Crandall Canyon Mine. All of the performance standards have been adhered to and met. Under the circumstances, no violations were issued. Several culverts need to be cleaned. These included from the MRP drainage map the following diversions; outlet of C-14, inlet of C-12, outlet of C-16, head and bottom of DD-13 and inlet of C-17.

SIGNS AND MARKERS 2.

The signs that were checked included the identification sign. Other markers included the disturbed area, topsoil, and stream buffer zone.

The permittee and Patrick Collins performed a vegetation study on the topsoil piles to determine if the markers may be removed. They will be sending an amendment to the Division, since the results were encouraging.

HYDROLOGIC BALANCE: DIVERSIONS 4A.

Checked all diversions and the following were in need of routine maintenance: outlet of C-14, inlet of C-12, outlet of C-16, conveyor shroud at the head of DD-13, sediment at the bottom of DD-13 and inlet of C-17.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The sediment pond was not discharging during the inspection and the water level was about 50% of capacity. There were no signs of any hazardous conditions occurring to the sediment ponds during the inspection.

HYDROLOGIC BALANCE: WATER MONITORING 4D.

The second quarter monitoring was completed for the following stations: Blind Canyon Creek, Horse Canyon Creek, Indian Creek, LF-1, UPF-1, SP1-19, SP1-22, SP1-24, SP1-3, SP1-47, SP1-9, SP2-1, SP2-24, SP2-9, SP-30, SP-36, SP47A, and SP-58.

HYDROLOGIC BALANCE: EFFLUENT LIMITATIONS 4E.

There are two UPDES stations 001 pond and 002 mine water. The June report was sent to the Division on June 27, 2001.

8. **NONCOAL WASTE**

There was a small oil spill on the lower pad that the permittee placed absorbent material to contain this small spill.

Inspector's Signature:

Nowberger #49 for wm. J. malencik Date: August 3, 2001

This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

sd

James Fulton, OSM cc:

Gary Gray, Genwal

Price Field office

O:\015032.CRA\Compliance\2001\p_072731.wpd